
























Carpenter Die Set List (Wezag)

Item-no.	Picture	Description	Terminal Examples
8731		Die for insulated terminals with brass sleeve 22 - 10 AWG	
8732		Die for fully insulated fastons (Ultra Fast AMP/Tyco) 26 - 14 AWG	
8733		Die for fully insulated fastons (Ultra Fast AMP/Tyco) AWG 12 / AWG 10)	
8734		Die for insulated butt connectors red/blue/yellow 20 - 10 AWG	
8735		Die for insulated flag terminals red/blue 20 - 14 AWG	
8736		Die for Cu tube and un-insulated terminals (Pin-Crimp) 26 - 8 AWG	
8737		Die for Cu tube and un-insulated terminals (W-Crimp) 22 - 10 AWG	
8738		Die for insulated and un-insulated ferrules 26 - 8 AWG	
8739		Die for coax BNC connectors for RG58/59/62/71 wire	
8740		Die for un-insulated 2,8mm quick connect terminals 20 - 10 AWG	
8741		Die for un-insulated 4,8mm quick connect terminals 20 - 10 AWG	
8742		Die for machined round contacts 26 - 12 AWG	